


Quick start


- Connect the supplied Dimlux USB device to your computer (windows)
- The USB device contains the software to run the Dimlux datalogger
- Find the installation software and double click the EXE file
- Install the software and follow the directions on your screen



- Click "more info" when this window appears



- Click "run anyway"
- The software creates a desktop icon on your computer



- Click the icon and the datalog window opens



- The software is now successfully installed on your computer

Preparing hardware

- First complete the full installation of the Dimlux Maxi Controller and all the sensors and lights.
- Connect the supplied Dimlux USB storage device to the USB port on the Maxi Controller
- When using a field supplied USB storage device, make sure you format it using the file system FAT32 and unit size 512 bytes. Do NOT use Quick format.



Start logging

- After the hardware setup is complete, press and hold the modus key on the Maxi Controller. The software will initialize the USB device and logging will start.
- By pressing and holding the modus key again the logging will stop.
- When the Maxi controller is logging, the green led next to 400watt will blink.
- It's possible to change the log-interval by scrolling the light-menu until you find log-interval. Press the set key and change the setting using the + or - key. Confirm using the set key.



Datalogger readout

-After data is collected on the USB device, connect it to your computer and click the Dimlux-Datalogger icon  on your desktop.

-The Dimlux datalogger window opens



-Click FILE > Import logfile



Browse to find the USB device, click the logfile and rename it.

